

## MSI Self Assessment NAVAREA XIX

Submitted by Norway

### SUMMARY

Executive Summary: Synopsis of activities within NAVAREA XIX since WWNWS 7

Action to be taken: Paragraph 12

Related documents: None

### 1. Background:

Limits of NAVAREA XIX:

From a position on the Norwegian coastland at 65° 00'.00N to:

65° 00'.00N, 005° 00'.00W,

75° 00'.00N, 005° 00'.00W, west to a position on the Greenland coastline;

From the border between Norway and Russia (Inland) to:

69° 47'.68N 030° 49'.16E,

69° 58'.48N 031° 06'.24E,

70° 22'.00N 031° 43'.00E,

71° 00'.00N 030° 00'.00E, further north along the 030° 00'.00E meridian to

90° 00'.00N 030° 00'.00E,

90° 00'.00N 035° 00'.00W, south to the Greenland coastline along the 035° 00'.00W meridian.

The broadcasting of SafetyNET messages will be addressed to a rectangular area until Inmarsat-C or mini-C terminals operating in arctic waters have been updated.

Navigational Warnings regarding positions at or above 76°N will be broadcast both on SafetyNet and on High Frequency Direct-Printing Telegraph System (HF NBDP).

NAVAREA Warnings: 0630UTC and 1830UTC (AOR-E), (HF NBDP)

Satellite SafetyNet broadcast service provider: Marlink

HF NBDP service provider: Telenor Maritime Radio

Operational Points of Contact for National Co-ordinators within the NAVAREA:

<i>COUNTRY</i>	<i>INSTITUTION</i>	<i>TELEPHONE</i>	<i>FACSIMILE</i>	<i>EMAIL</i>
Norway	Norwegian Coastal Administration	+47 22422331	+47 22410491	navco@kystverket.no

**2. Comments:**

The GMDSS Master Plan (GMDSS.1/Circ.19) is up to date regarding NAVAREA XIX. The most recent update was provided in connection with IMO NCSR 3, March 2016.

The following table shows equipment installed with NAVAREA XIX operations room:

<b>Equipment Type</b>	<b>Software Version</b>	<b>Date of Up-date</b>
Sailor TT-3026D/S/M maritime mini c	Easymail v1.16	-

The following table shows specifics of information and data received:

<b>2013</b>				<b>2014</b>				<b>2015</b>			
E-mail	Fax	Phone	Text	E-mail	Fax	Phone	Text	E-mail	Fax	Phone	Text
334	N/A	315	N/A	360	N/A	365	N/A	310	N/A	305	N/A

The following numbers of navigational warnings were promulgated via SafetyNet:


	<b>2013</b>	<b>2014</b>	<b>2015</b>
<b>NAVAREA XIX</b>	<b>126</b>	<b>146</b>	<b>122</b>

The following table shows details of the numbers of NAVAREA warnings identified as immediate priority (requiring transmission within 30 minutes) and the average elapsed time per broadcast via SafetyNET:

<b>2013</b>		<b>2014</b>		<b>2015</b>	
Total	Average elapsed time	Total	Average elapsed time	Total	Average elapsed time
0	N/A	0	N/A	0	N/A

NAVAREA XIX received 14 requests for a list of in-force navigational warnings in 2015.

### 3. NAVTEX Coverage:



NAVTEX Stations in NAVAREA XIX:

B <sub>1</sub>	Station	Telephone	Fax	E-mail	Operational status
A	Svalbard	+47 75 52 89 25	+47 75 52 58 96	bodo.radio@telenor.com	Confirmed
B	Bodø	+47 75 52 89 25	+47 75 52 58 96	bodo.radio@telenor.com	Confirmed
C	Vardø	+47 75 52 89 25	+47 75 52 58 96	bodo.radio@telenor.com	Confirmed

### 4. Operational Issues:

Coastal State/Country	Number of MSI messages	Topics/Subjects of messages
Norway	3	Aids to navigation

A new HF NBDP service will be established at Hammerfest during autumn 2016, replacing the current service at Svalbard.

Number of messages issued by HF NBDP 2015: 1

In force warning bulletins are issued once a week.

Warnings in force older than 42 days are available on the NAVAREA XIX website.

## 5. Quality Management Survey

NAVAREA	ISO 9001 - 2008	Promulgate "In-Force" Bulletins	Promulgate "No-Warning" Messages	Monitor Broadcast	24/7 contact information provided	Promulgate two scheduled broadcasts	IMO Master Plan updated
XIX	NO	YES	YES	YES	YES	YES	YES

## 6. Contingency Planning

Contingency procedures and systems are established and regularly tested.

## 7. Capacity Building:

Nil.

## 8. Other Activities:

Nil.

## 9. NAVAREA Website:

NAVAREA XIX warnings in force: <http://www.navarea-xix.no/>

The website is updated in connection with the promulgation of navigational warnings via GMDSS.

The date and time of the last update is not displayed on the web site.

## 10. NAVAREA Contact Information:

No change.

## 11. Recommendations:

Nil.

## 12. Actions requested:

The Sub-Committee is invited to note the report.

## 13. Summary:

NAVAREA XIX Coordinator introduced the Self-Assessment Report covering the period since WVNWS7. There are no significant changes regarding NAVAREA XIX since the previous report to WVNWS 7.