

#### **Hydrographic Services and Standards Committee**

Report

to

HSSC-4, September 2012

Decisions of other bodies affecting HSSC: IMO

#### Past and upcoming meetings

- Maritime Safety Committee (MSC)
  - MSC90: 16-25 May 2012 (CL 57/2012)
  - MSC91: 26-30 Nov 2012
  - MSC92: 12-21 Jun 2012
- Sub Committee on the Safety of Navigation (NAV)
  - NAV58: 02-06 Jul 2012 (CL 70/2012)
  - NAV59: 02-06 Sep 2012
- Workshop on resolving operating anomalies in ECDIS
  - 2<sup>nd</sup> Workshop: 25-26 Jan 2012 (CL 18/2012)
  - 3<sup>rd</sup> Workshop: 15-16 Oct 2012 (CL 74/2012)



### Issues relevant to HSSC (1/2)

- Development of an IMO e-navigation Strategy
  - contribution to the on-going work of the IMO e-navigation correspondence group
    - gap analysis
    - description of the e-navigation architecture
    - development of a strategy implementation plan
  - use of S-100 as the baseline standard endorsed by MSC90
  - IMO/IHO Harmonization Group on Data Modelling authorized by MSC90 (dormant for the present)
- New symbols for AIS aids to navigation
  - IMO Correspondence Group in progress to report back to NAV59



# Issues relevant to HSSC (2/2)

- Operating anomalies in ECDIS
  - Publication of an IHO data presentation and performance check
  - Analysis of reports of checks of nearly 900 installations
    - ECDIS manufactured and approved after 01 Jan 2009 appear to meet the relevant standards
    - The majority of ECDIS sold before 01 Jan 2009 require some sort of software upgrade; in most cases, operational "work-around" solutions can be implemented until the upgrade is applied; mariners alerted to specific situations through NAVAREA warnings and Notices to Mariners
  - Progress in resolving the issue with OEMs generally positive, except for some legacy systems that are no longer supported
  - Continuing action required
    - continue to improve the clarity and consistency of IHO standards => HSSC
    - continue to monitor the situation and coordinate efforts => IHB



## Action required of HSSC

- a) note the reports,
- b) consider if further practical measures can be taken by the IHO to ensure better coordination among the ECDIS stakeholder community and the provision of information to the mariner; and
- c) take any other action as considered necessary.

